

## MULTI-CARRIER SIM Certified Devices

Manufacturer	Model	Firmware
2N	2N Gateway	1.5.0.0.4
Actia	In house	REVISION 01.002 A-REVISION 01.000.05
Advantech	UNO-2372G-J121AU	Ubuntu desktop 18.04
Advantech	MIC-7500 – Intel i7 6822EQ	Ubuntu desktop 18.04
Advantech	SmartHand SR305	03.017 / 6.2.8
Advantech	FWA1112	eNetOS 1.2.8
Advantech	ICR 2041	6.3.10
Albeego	Atom	Linux 1904
Alcatel	Linkkey 4G LTE	IK41_RD_02.00_05
AMIT	MDG200-0T001	EC25AFFDR07A09M4G
Apple	iPad 9.7	iOS version is 16.3.1
ASUS	PE100A	Path: /org/freedesktop/ModemManager1/Modem/0 Manufacturer: QUALCOMM INCORPORATED Name: QUECTEL Mobile Broadband Module Version: EC25EFAR06A08M4G
Atel	Arch W01	QC25_W01_1.0.6.901

ATT USB800	ATT USB800	Embedded OS version2.114.0.18.6Modem firmware versionSDx20FAT-1.30.0.17 1 [2020-05-15 07:02:39]PRI version107
BEC	MX-210NP	1.04.1.464.3
BEC	MX-210NP	1.04.1.518
Bluebird	ST102	ST102
BTU Research	Baxton2	20210704
CalAmp	LMU 3641	V8.6a
Cardlepoint	E300	Netcloud 7.21.30
Caterpillar	S42	LTE_C01091.10_NE_S44G_0.036.01.00
Chainway	c72e	Android 8.1.0
Chainway	C66	C66_US_V2.00_20210727
Checkpoint	1570	Build: R81.10.00_996000575, OS: System, GAIA Embedded
Cinterion	Cinterion PLS6-W	2.0
Cipher Lab	RS35	Android 10
Cisco	809	SWI9X15C_05.05.58.00
Cisco	Cisco Meraki PLAS9-X (T3 NA)	MG 1.9

Cisco	MX68CW	MX 14.53
Cisco	MG41	MG 2.0
Cisco	MG21	MG 1.9
Cisco	Meraki M67C	MX16.6
Cisco	1100	17.9.4
Clear ISA	N50	Android 9
Clover	C401U	0 02.02.0634 02.05.0196 (01.00476)
Clover	Flex Gen 3	MC116_NA19001.1000.00.02.20.20
Compulab QUALCOMM INCORPORATED	SIMCOM_SIM7600G	LE20B03SIM7600M21-A / HW: 1000
Cradlepoint	E300	72180
Cradlepoint	Cradlepoint IBR900/600-M	24.01.516_Generic,1025
Cradlepoint	E300	7.2.6.0
Cradlepoint	E300	7.2.5.0 2020
Cradlepoint	IBR600C	NetOS 7.2.20
Cradlepoint	E100	7.21.20

Cradlepoint	IBR900/600-M	24.01.513_Generic,1016
Cradlepoint	IBR600C-150M	7.9.1002.1002_GENERIC,201905141
Cradlepoint	AR2200	7.2.1.0
Cradlepoint	1200M-B/C18B	32.00.156_NAmerica-GN.5005
Cradlepoint	C7	SWI9X50C_01.14.03.00 b06bd3 Jenkins 2020/09/23
Cradlepoint	600M	24.01.511_Generic, 1009
Cradlepoint	W4005-5GB	SWIX55C_01.07.13.00_Generic,016.006_000
Cradlepoint	150M-D/C4D	EC25AFFDR07A07M4G_01.003.01.003
Cradlepoint	E3000	32.00.116
Cradlepoint	IBR900	Generic 24.01.516, 1025
Cradlepoint	AER2200	7.22.10
Cradlepoint	IBR1700-600M / MC400-1200M-B	24.01.516 / 32.00.116
Cradlepoint	L950	7.21.70
Cradlepoint	W1850	Netcloud 7.21.91
Cradlepoint	R1900	7.22.10

Cradlepoint	IBR1700	24.01.516_Generic,1025
Cradlepoint	E3000-C18B	fw 7.22.30 modem fw 01 07 19 00
Cradlepoint	IBR 900	7.21.91
Cradlepoint	W1850	W1850 - 5G
Cradlepoint	W1850	v7.22.40 / SWIX55C_01.07.13.00 000000 jenkins 2020/12/16 22:24:13
Cradlepoint	AER2200	7.1.20
Cradlepoint	E3000	7.22.20
Cradlepoint	IBR900	7.21.91
Cradlepoint	IBR 900/600	7 22 60
Cradlepoint	E3000	7.22.1
Cradlepoint	IBR650C-150M-D	: 7.10.1003.1003_GENERIC, 202108201
Cradlepoint	W4005-5GB	SWIX55C_01.07.13.00 000000 jenkins 2020/12/16 22:24:13
Cradlepoint	1850	7.22.10
Cradlepoint	E3000	7.01.07.13.00 Generic
Cradlepoint	W2005	7.22.10

Cradlepoint	1200M-B	7.2.1
Cradlepoint	IBR200 (AT&T)	7.22.50
Cradlepoint	W2005 - E3000	NOS 17.22.6
Cradlepoint	R1900	7.22.80
Cradlepoint	E3000	7.22.80
Cradlepoint	CBA850	02.20.03.00_GENERIC,002.017_000
Cradlepoint	E300	32.00.113
Cradlepoint	E3000-5G	03.09.11.00_GENERIC,030.044_004
Cradlepoint	R1900	03.09.06.00_GENERIC,030.038_000
Cradlepoint	R1900	03.09.11.00_GENERIC,030.044_004 / SWIX55C_03.09.11.00 7bf975 jenkins 2022/06/10 20:36:01
Cradlepoint	W4005-5GB	03.09.11.00_GENERIC,030.044_004
Cradlepoint	E300	01.14.03.00_GENERIC,002.036_010
Cradlepoint	W2005	Modem FW Version:03.09.11.00_GENERIC,030.044_004
Cradlepoint	E300	03.09.06.00_GENERIC,030.038_000
Cradlepoint	E300 5G	03.09.11.00_GENERIC,030.044_004

Cradlepoint	IVR600	7.10.1004.1004_GENERIC,202108201
Cradlepoint	R920	FW: 7.23.20/Modem FW: 01.14.03.00_GENERIC
Cradlepoint	MC400 1200M-B	Modem FW 32.00.118_EuAPAC-GN,1027
Cradlepoint	CPA850	7.23.30
Cradlepoint	E300	03.10.07.00_GENERIC,030.062_000
Cradlepoint	E300	7.23.50
Cradlepoint	IBR900-1200M-B	v7.22.60
Cradlepoint	W1850	7.23.60
Cradlepoint	E300	03.09.11.00_GENERIC,030.044_004
Cradlepoint	1850	03.09.11.00_GENERIC,030.044_004
Cradlepoint	W2005-5GB	OS: System, FW Generic 03.10.07.00_GENERIC,030.062_000
Cradlepoint	S700-84B	OS: System, 7.10.1004.1004_GENERIC,202108201
Cradlepoint	IBR600C	7.2.40
Curlink	Load Sensing LSG6-KIOGW	2.4.1
Custom	T8 Tablet	alps-mp-r0.mp1-V8.228 / V003.0A.01

Datalogic	Marmor10	Android 9
Datalogic	Marmor 20	Android 9
Datalogic	Memor 11 (Pre-production Alpha Build)	Android 11 / 0.00.05.20220928
DataRemote	CDS-9010	V3.10(R202103131019GN.4-MIX_V1.3.3T)
Dataremote	9090	V0.6.12(R202111061438EN.2-MTL)(MAR.2.0.0N)(rtf3.0.0n)
DataRemote	DR9010	Device Firmware: V3.10(R202205131057EN.4.1-MTL_V1.5.7.3T); Modem Firmware: MAR.2.0.0T
Dejero	GateWay M6E6	2.2.6.3467
Dejero	EM7511	3.0.0.4675
Dell	DW5821E	Windows 10, Build - T77W968.F1.0.0.5.2.VZ.013044
Dell	5424 - T77W968	Win 10
Digi	DX6310	WBU_Current Config_20210720
Digi	XB3	Digi 31015 / 23.00.306
Digi	IX20W	21.2.39.67
Digi	EX15 CAT 18	22.5.50.62
Digi	EX15	24.01.513_Generic Revision24.01.513SKU



Digi	EX15 CAT 7	22.5.50.6201.14.03.00_GENERIC_002.036_000
Digi	EX15 CAT 6	22.5.50.62/02.20.03.00_GENERIC_002.017_000
Digi	IX30	21.5.56.106
Digi	Inseego 8800L	2N
Digi	EX50	22.11.48.17
Digital Matter	G70	1.3 -> 1.7
Digital Matter	Dart3-4G	1.4 -> 1.11
Dolphin	CT60	Android 8.1.0
dongjixiaomage	Seuic Cruise 2 5G	OS – Android 11, Build - D740_G_V1.1.94_debug
DriveU	DU10	SWI9X50C_01.11.00.00 5ba42f jenkins 2019/06/28 09:51:52
Dynafire	MOfi4500 v2	2017
ELPRO	EL-641M-2	1.1.7 (56881f4)
Evolve	Primal Droid 48	Android 11
Field Payload	3	ModemManager 1.10.0
FireM	M199	OS: Free BSD 12.3-NIW-2022-02-21 ,FireM Firmware - 6.029

FireM	M366	OS: Free BSD 12.3-NIW-2022-02-21 ,FireM Firmware - 6.029
FireM	TRB140	TRB1 R 00.07.03.4
FireM	TRB140	TRB1 R 00.07.03.4
FireM - Raspberry PI	FM-0002	FreeBSD 13.1
FireM - SIMCom	SIM7600G-H	OS: v13.1-NIW-2023-01-30 , FW: v6.034
FireM, Rasberri Pi	MEPTEK 55	Free BSD 12.2 / 1.001 Dated (7/12/2019)
Flexworx Data Remote	CDS-9010	EC25AFFDR07A07M4G
Fortigate	FortiExtender 211	7.0
Fortinet 201E	AirPrime EM7455	Firmware version 4.1 build 159!
FOXXD	T8 Tablet	T8V1
G10	C4R400	0b07
GE	MDS ECR	8.0.7
Geshem Technology	TPC-GS0881T	TPC-0881T_V1.01_20230403
Getac	Getac ZX-70	Z.0.6.107.5.0
GL Inet	Mifi	(internal version mifi-wan-wifi-cellular-0.1-1

GL-Inet	Spitz v2	spitz-v2-wired-wifi-cellular-dev-1.0-9 / OpenWrt 19.07.7, r11306-c4a6851c72 / GL-iNet version: 3.203
Google	3 XL	Android 12 / SP1A.210812.016.C1
Google	Pixel 6	Android Version 12 Build number SP2A.220305..013.A3 SKU 6483635 Model GA02900-US
Google Chromebook CTL	NL71-L	98.0.4758.107
Higher	AeroQ	Build 289
Hikvision	SolarCamera / DS-2XS6A87G1-L/C32S80	V5.7.0 build210705
Hitachi-Tropos	TRO620	9.1.0.10
Honeywell	CN75	03.320
Honeywell	CT60	Android 9
Honeywell	RT10	Android 9
Honeywell	CT40XP	Android 9
Honeywell	CN80	Android 10 / 90.00.06-(0164)
Honeywell	CT45P	Android 11 / 311.C0.04.0146-G
Honeywell	CT60	android 9 build number 88.00.21-(0210)
Honeywell	CT47	Android 12 , Build 412.01.02.0029G

Honeywell	CN85	86.00.30-(0195)
HongDian	H8956-4GSPT	V7.0.3_SE_America_180803
HP	Elitebook X360 1040G7	18500.5001.00.03.25.18
HP	Engage Go Mobile Sytem	Windows 10
HP	HP Intel XMM7560R+ LTE-Advanced Pro	Windows 10 Version 21H2 OS build: 19044.1503
Huawei	P40 Lite	Android 10 (SDK 29) 10.1.0.202C10
iMotion Opticon	H33	Android 9 / PR02.200505.002
In Hand	IR305	Current VersionV1.0.24 Current Bootloader Version1.1.3.r4955
Ingenico	Move/5000 4G	ELS81
Ingenico Move	5000	0390
Ingics	IGS03M	IGS03M-v1.1.0.0
Inhand	IR302-FQ33	3.3.0.r5303 / 1.1.3.r4954
Inhand	InRouter 302 Compact Industrial LTE Router	V3.5.31
InHand	IR305-FF38	V1.0.46
InHand	IR305-FQ39	V1.0.46

InHand	ER805-NRQ3	V2.0.11
InHand	VG710-H-NRQ3	V1.2.1.r30053
InHand	IR302-FQ38	V3.5.57
InHand	IR302-FQ02	V3.5.57
InHand	IG502-FQ33	V2.0.5
InHand	IG902-FS39	V2.0.5
InHand	VT320-FQ02	VT3_V1.1.44
InHand	IR302-FQ33	3.5.59
InHand	IR305-FF38	1.0.1.28
InHand	IR302-FQ38	3.5.63
InHand	Router 301	V3.5.59
Inhand	MoCR202-NAC6-WLAN-Bdel	OS: System, Build V1.0.12
InHand	IR302	3.5.66
Inhouse	AQS LTE EU	246.97
Inhouse	Micro IoT	1.353

Inrico T290	MP22	Android 8.1.0
Inseego	S2000e	SDX55MOR-2.41 1 [2021-02-08 22:59:08
Inseego	USB8	Embedded OS version2.114.0.18.6Modem firmware versionSDx20FAT-1.30.0.17 1 [2020-05-15 07:02:39]PRI version107
Inseego	MiFi 8800L VZW	1.S
Inseego	S2000E	SDX55MOR-2.52 1 [2021-09-26 23:59:06]
Inseego	FX2000e-3	2.409.1.2
Inseego	USB 8	2.114.0.18.6/PRI107
Inseego	Skyus 160NE	Device Firmware: 2.8;Modem Firmware:SWI9X30C_02.33.03.00 r8209 CARMD-EV-FRMWR2
Intuicom	XC400	3.0.0
Intwine Connect	ICG-150	3.5.34
IOT	Inhouse	To be added
Ipetronic	Ipelog 2	SWI9X50C_01.08.04.00 dbb5d0 jenkins 2018/08/2
iSafe	IS530	Android 10 / EV3124
iSafe	iS530.1 Smartphone	Android 10
iSafe	655.2	Android 10

iSafe	IS930.1	Android Enterprise 10, Build: IS930_Q_ROW_1.0.0.0.0_9_20230315
JACS	TD191	Universal
JACS	TD0301	Universal
Janam	XT3	Android 9 / 91.08 (May 20 2021)
Janam	XT2	87.13 (May14, 2018)
Janam	XG4	42.04 (Aug 24, 2021)
Janam	HT1	Android 9
Janam	XT200	8.1.0 / 84.07 (Nov 28, 2020)
Janam	XT30	9 / 20.01A1-20211103
Karchan	SAD1010S	OS: android 11, Build: 2.0
Kiloview	P2	Fw:2.5.0, SW:4.7.2529
Lantronix	Lantronix SAM9X60-2 Bootstrap 2.1.0.0R2	Lantronix X300 1.8.0.0R4
Lenovo	500eChromebook Gen 3	Firmware Version: 106
Lenovo thinkpad x1	HAH-PF493PA4	Windows 10 version 21H2 os build 19044.1620
Lenslock	MDVR	V3h0404_B351_T220527.95.NULL

Lenslock	Gen 13 bodycam	944_v330_T220926.02.B1
LiveU	LU800	OS: 10.0.1.C2935.G02aba7377
LK GPS	LK209	MyKeeper_PSN2022/08/15
Maxwest	Ultra 8	Android 11
Maxwest	MX-GG6	Android 12
MC Communications	TK920 Deskcell	2.7.5.d8950
MeiGLink	SLM750	SLM750-V_5.57.20_EQ101
Meraki	MX68CW	MX 15.44
Microhard	ipn4gii	1.2.0 / build r1112
Microhard	Bullet NA2	1.2.0 / r1120
Microhard	LTECube-CAT4-NA2	: v1.5.0-r1044
Microhard	BulletPlus_NA	1,3,0 build 1084
Microhard Bullet LTE	NA2	Build R1108 7 HW: Rev1
Microhard Bullet LTE	Bullet NA-2	v1.2.0-r1120
Microsoft	Surface Pro 7+ I5 128/256GB	EM12GPAR01A09M4G_MSFT



Microsoft	Surface Go	Windows 10 V1809 OS Build 17763.973
Microtronics	300981	01.026
MikroTik	RB912UAG-5HPnD / RUT240	7.1rc3
Milesight	UR32-L00E-P-W	fw: 32.2.0.36 hw:V2.1
Mitel	Inhouse	2.0.4
Minisys	N10	eNetOS 1.2.8
Motorola	TLK100	BLUE_BASE_USR_R03.05.01_APPS_R03.05.02
Moxa	3111	1.51
Moxa	UC-3111-T-US-LX	1.7
MP-70	Sierra Wireless MP-70	ALEOS MP70 LWM2M (4.12.0.028)
MSI	Rugged Tablet ND52 - Gen 2	Android 9, Radio module FW:EM06ELAR03A08M4G
MultiTech	MTQ-LNA7	Board: B02 / EG95NAFBR05A04M4G
MultiTech	LNA7	5.3.5
MultiTech	LNA7	5.3.5
Multitech	MTCDTIP2-L4E1-B11EKP-L1M	5.3.8

Multitech	Dragonfly MTQ-LAT3-B02.R2A	20.00.525
Nayax	Telit HE910-GL	12.00.108
Nayax	Home made	4.0.0.23
Netgear	MR1100	NTG9X50c_12.05.05.14
Netgear	Nighthawk MR5200	NTGX55_12.04.10.01
Netgear	AIRCARD 797 Mobile hotspot	NTG9X40C_30.00.08.06
Nexar	N1	See comments
NimbeLink	NL-SW-LTE-TC4NAG	Can't find it in the device
Nodegrid Services Router (NSR)	NSR-BASE-SAC-POE	Build: SWI9X50C_01.14.13.00, OS: System
Novatel	Novatel USB 730L	B16.NVT.USB730L.0
NUU	Tab 10	Android 11
OnePlus	Nord N200 5G - DE2117	Android 11, Build: De2117-11-C.16
Outdoor Router	EZR33L 4G-LTE	SWI9X30C_02.33.03.00 r8209 CARMD-EV-FRMWR2
Palo Alto	ION 1200	Build: ION 1200-c-na 024701-000679-5686, OS Version: Sytem,6.2.1-b3
Panasonic	Toughbook CF-33	OS: Windows 10, Build: 22H2

Pantech	Verizon 4G LTE USB Modem UML295	L0295VWEA31F B5
PAX	E700	E700_PayDroid_7.1.2_Scorpio_V10.0.10_20200928
PAX	A800	PayDroid_10.0.0_Eucalyptus_V20.1.06_20221117
PAX	IM30-4G-BW	IM30_A80_PayDroid_7.1.1_Taurus_V05.3.32_20230803 - Android 7.1.1
Peplink	Max Transit 5G	8.1.2s007 build 5115
Peplink	Max BR1	8.1.1
Peplink	Balance 30 Pro	8.1.2
Peplink	Max BR1 Mini	8.1.2 build 5054
Peplink	MaxBR1	8.2.0 / b 5066
Peplink	Transit Duo	8.2.0 / b5312
Peplink	Balance 20X	8.1.3
Peplink	BR1 Mini	8.2.0 build 4901
Peplink	MAX-BR1-PRO-5GH-T-PRM	8.3.0
Peplink	BR1	6.3.5
Peplink	Max BR1 5G	8.2.0 build 4961

Peplink	Pepwave MAX Dome Pro	Build: 8.30s052 Build 5265
Peplink	Max BR1 PRO 5G	8.2.0
Pepwave	Speedfusion Engine	8.0.2 / b3612
Pepwave	Max BR1 Mini CORE	8.1.3 build 5077
Pepwave	MAX BR1 M2M	8.3.0 build 5256
Pioneer	T5	6301.28.01
Pioneer	T5	Android 9 - 6301.28.01
Point Mobile	PM30	Android 10 30.04 (11/11/2022)
Point Mobile	PM67	67.04 (11/18/2022)
Point Mobile	PM90	90.52 (10/21/2022)
Point Mobile	PM75	75.03 (07/08/2022)
Point Mobile	PM86	Android 11, Build 86.00 B5 (May 27 2023)
Protectli FW2B - 2 Port Intel® J3060 Vault: FW2B - Core Unit	4G LTE Internal Modem	Windows IoT / SWI9X30C_02.33.03.00
Quectel	One Point Quectel Device	NA
Quectel	Pureflo IOT Board	Firmware Version:1.0

Quectel	Pureflo IOT Board	Firmware Version:1.0
Quectel	EC25-EUX	Android 10, Build - D700S_G_V0.5.6
Quectel	SC20-AX	0.00.19.000
Quectel	EM12	EM12GPAR01A20M4G
Quectel	RM520N-GL	RM500QGLABR11A06M4G
Quectel	BG600L	BG600LM3LAR02A04_01.200.01.200
Quectel	EG25-G	Option LTE WW Rev 4 Firmware - 2.98.3
Quectel	EM05-G	EM05GFAR07A07M1G
Quectel	BG96	GEOCLICNWB_C4H-3.05019001 / BG96MAR02A10M1G
Quectel	Quectel EC25-EC	OS: RutOS (OpenWrt based Linux OS) 5.4.147 EC25ECGA-128-SNNS, Firmware build date : 2022-07-19 10:46:51
Rack Wireless	Wizgate Edge Pro	1.3.4_rackb113
RAD	SecFlow-1v	SF_0290_2.3.01.42.tar
Rak Wireless	RAK7249	1.2.0065_Release r209
Readynet	LTE520	EC25AFAR05A04M4G
Readynet	LTE200	EC25AFXDGAR07A01 M1G

Readynet	LTE520S	V3.36 (202107221622)
Readynet	LTE 520S 4G LTE 300Mbit/s	V3.36 (202205171419) Hardware Version V3.2
ReadyNet	GSX1204	GSX1204_v2,14ac4_202210121836
Readynet	LTE520S	3.3.6
Red Lion	SN-6910-VZ	SWI9X15C_05.05.58.00 r27038
Redlion	SN-6901EB-AT	4.29B / Revision: SWI9X15C_05.05.58.00 r27038 carmd-fwbuild1 2015/03/04 21:30:2
Rhino Mobility	Rhino	Android 9
Roar Engineers	ROAR Gateway 2.0	0.1.15
SAGEMCOM	HI3GC	A.001.31
Samsung	Tab A - ATT Model SM-T387AA	Android 10
Samsung	Tab A - Vzw Model SM-T387V	Android 10
Samsung	Samsung Tab A SM-T587P	8.1.0
Samsung	Tab A7	es
Samsung	Tab A	Android 10
Samsung	Active Tab 2	Android 9

Samsung	Galaxy A10e	Android 9
Samsung	Galaxy Tab 7	Android 10
samsung	Model SM-T725	Android 10
Samsung	S8	Android 9 Build Number PPR1.180610.011.G950U1ES8DTJ1
Samsung	A51	Android 10, QP1A.190711.020.A515U1UES3AT11
Samsung	Tab A	Android 9 PPR1.180610.011.T307USQU1ATCB
Samsung	A12	Android 10
Samsung	A21	Android 10
Samsung	Tab Active 2	Android 9
Samsung	A02s	Android 10 / RP1A.200720.0123A025U1UEU1BUI1
Samsung	A11	Android 10 / RP1A.200720.012.A115USQU5BUH1
Samsung	Active Tab Pro	Android 11 / RP1A.200720.012 T547UUEU5CU12_B2BF
Samsung	S21 5G	Android 12 SM-G991U
Samsung	Tab 7 / SM-T505	Android 11
Samsung	XCover Pro	Android 11

Samsung	S22 Ultra	Android 12
Samsung	Tab A 7 Lite	OS – Android 11 Firmware Build – RP1A.200720.012.T227UVLS2AVE1
Samsung	Samsung S7	Android version 8.0.0
Samsung	Galaxy A12	Android 11
Samsung	Galaxy Tab A 8.4	OS11 Build: RP1A.200720.012.T307USQU8CVE1
Samsung	A42	Android 12
Samsung	Active 2 SM-397U	Anoid 9 PPR1.180610.011.T397UUEUCCVF2
Samsung	SM-T577U	Android 12, Build - SP1A.210812.016.T577UUES3CVH1
Samsung	Active Pro SM-7547U	Android 10 Build - RP1A.200720.012.T547UVLU8CVI2
Samsung	A7 Lite SM-T227U	Android 11/Build – RP1A.200720.012.T227UVLS2AVE1
Samsung	Galaxy S10e	NA
Samsung	A54/SKU SM-A546U1	Android 13
Samsung	Galaxy Tab Active4 Pro 5G - SM-T638U	Android 12, Build: SPE2A220305.013.T638UUEU1AVH6
Samsung	S20 FE / SM-G781U	Android 12, Build: SP1A.210812.016.G781USqs9FvK2
Samsung Tab Active 2	SMT397UZKE	3.18.91



Santok	STK X3	Android 11
Secomea	Site Manager Model 1539	v1539_622465022 [10.0.622465022(fetched 2022-12-02)]
Secomea	Site Manager 1539/3539	v1539_323223481
Seuic	Cruise2A	Android 11 / D730_G_V1.0.0
Seuic	Cruise 2 5G	Anroid 11, D740_G_V1.1.94_debug
Sierra Wireless	Airprime MC7455	Need further input from customer
Sierra Wireless	RV50 - NA	MC7354_05.05.58.00_GENNA-UMTS_005.025_002
Sierra Wireless	LX40, NA, WiFi Part# 1104573	SWI9X07Y_02.28.03.01 000000 jenkins 2019/04/17 03:08:11
Sierra Wireless	LX40	SWI9X07Y_02.37.06.00 b91e64
Sierra Wireless	MC73355	05.05.58.00_GENNA-UMTS
Sierra Wireless	EM7455	SWI9X30C_02.38.00.00 rE3F3E55C03AE94
Sierra Wireless	MC7411	01.14.03.00
Sierra Wireless	RV50X	ALEOS RV50X LWM2M (4.16.0.021)
Sierra Wireless	RC7611	SWI9X07H_00.08.20.00 d73df7 jenkins 2021/10/14 00:48:45
Sierra Wireless	MP-70	OS: ALEOS MP70 LWM2M, Build: 4.16.2.001

Sierra Wireless, Incorporated	MC7354	v4.29
Social Mobile	Rhino Pace 1	Android 11 PACE_A1(005)_20220919
Social Mobile	T5se	Android 11 T5se(001)_20220624
Sonim	XP8 (XP8800)	Android 8.1.0
Sonim XP5800	Sonim XP5800 VZW	Android 8.1.0
Stream X	X3 4.0	x3 se v270_t200904.03
Sunmi	V2s	build 3.0.11 firmware number: 242
Sunmi	P2 Pro	Android 7.1.2
Surfsight	AI-12 Connected Dashcam	3.9.207
SurfSite	AI-12	Android OS
Systech	Cisco 2000 Cellular Gateway	EC25AFFAR07A08M4G
Talearis	XPID100-V01-B2N-F0	Android 7 / XPID100-V01-B2N-F0CV717P30LL1CT1SY2MUSP01_mipi_private_key
Talearis	C6	Android 10 / C6.QV10.3.13_0.N0_EEA
Talgil	Sapir 2 4G	New Beta (pending specific ver. from customer)
Telit	LE910C1-EU	C1EU4G3G2G v25.20.226.10

Teltonika	RUTX11	RUTX_R_00.07.02.1
Teltonika	RUT240	RUT2XX_R_GPL_DBT.01.14.1 / Firmware build date 2021-10-26, 13:42:21 / Kernel version 3.18.44
Teltonika	RUTX11	261
Teltonika	Tier B 1140	Firmware version TRB1_R_00.07.02.3 Firmware build date 2022-06-23 06:55:57 Internal modem firmware version EC25EUGAR06A05M4G_BETA1108 Kernel version 3.18.20-msm
Teltonika	RUT955	RUTXX_R_00.06.06.1
Teltonika	RUT955	RUTXX_R_00.06.06.1
Teltonika	RUT955	RUT9XX_R_00.06.09.2
Teltonika	RUT240	RUT2_R_00.07.02.4
Teltonika	RUTX11	See notes - important
Teltonika	RUT 240	Build: RUT_R_GPL.00.07.02.4
Teltonika	RUT 240	FW: UT2XX_R_00.01.14.5, Device OS/Kernel version: 3.18.44, Build: RUT24006B000
Teltonika	RUTX50	Firmware version RUTX_R_00.07.03.3 Firmware build date 2023-01-24 08:53:06 Internal modem firmware version RG501QEUAAR12A07M4G_04.001.04.001 Kernel version 5.4.221
Teltonika	RUTX12	RUTX_R_00.07.04.5
Teltonika	TURX50	RUTX_R_00.07.04.5
Tickiot	850FD	2.7.5D8950

Tickiot	TK920+	2.7.5.d8950
Tickiot	MC Comm 801	Android 5.1.1 Build Number 1.0.144
Tosibox	675	1.3.1
Touch Dynamic	Quest VIII	SW19X30C_02.24.05.06
TOUCHSTAR	VH401	Astro LEDE-Reboot-17.01.6 BUILD012 r3979-2252731af4 / LuCI lede-17.01 branch (git-18.201.27126-7bf0367)
TP-Link	TP Link X20-4G	1.0.5 Build 20210708 Rel. 64376
TVU	TM1000V3	Will get back to us with this
uBlox	SARA-R510M8S	02.06,A00.01 Device name: CB22 Device model: CB22 Device firmware: 2.4.0
u-blox	SARA-R410M-02B-03	L0.0.00.00.05.12,A.02.19
u-blox	LARA-R6001D	00.13,A00.01
u-blox	SARA R410M-02B-03	02B-03
Unistrong	UT12P	RP00.53.84.16
Unitech	WD200	Android 10
Unitech	EA630	Android 10
Unitech	HT730	Android 10

Unitech	EA520	Android 11
Unitech	W01-T	Android 12 Build - ANNA_MP_V06.0_2_20220629_user
Unitech	HT330	Android 12 - ANNA_MP_V06.0_2_20220629_user
Unitech	EA630 Plus	EMMAII_V0.16.0_20211230_userEMMAII_V0.16.0_20211230_user
Uplogix	LM83x	6.2 / 20210831:232419 / OS Version: 6.2.0.38768
Urovo	DT50S	SQ53S_WE_DS_U_2022-04-24, OS: Android 11
VMWare	Edge 610-LTE	4.3.1 [R431-20220720-GA-70933-76564-74149-f10431c72c] / SWI9X50C_01.11.00.00 5ba42f jenkins 2019/06/28 09 51 52
VMWare	510-LTE	"Firmware Revision": "SWI9X30C_02.30.03.00 r7804 CARMD-EV-FRMWR2 2018/07/25 01 10 04", "Hardware Revision": "1.0",
Wago PLC	750-8217-600-000	Wago Firmware: 03.06.09(18)
Wasp	DR6	Android 12, Build: RAYA_V04.42b01_20230228
Wasp	DR5	Android 10, Build: HEBE10.MR3.0007.3.20210527
WHOOP	LTE USB MODEM WHT25LT	V2.0
Winmate	FM12 AD-V	Windows 10
WizarPOS	Q2	Build - 1.0.0-4700 Android 7.1
Yeacomm	P21	P21_1.44

Zebra	EC55	Android 10
Zebra	ET56	Android 8.1.0
Zebra	ET56	Android 10
Zebra	EC55	Android 10 / 10-16-10.00-QG-U15-STD-HEL-04
Zebra	TC77HL (TC77)	Need further input from customer
Zebra	RTL10B1	8.1.0
Zebra	MC2700	Android 10 / 10-16-10.00-QG-U00-STD-HEL-04
Zebra	TC58	11-11-22.00-RG-U00-STD-ATH-04
Zebra	TC77HL	Android 10
Zebra	TC75	Android 8.1.0 Build - BSP: 02-52-21.00-OG-U04-STD
Zebra	ET45	Build - 11-13-06.00-RG-U00-STD-GSE-04
Zebra	TC57	11-26-05.00-RG-U04-STD-HEL-04
Zebra	TC57x	11-26-05.00-RG-U04-STD-HEL-04
Zebra	ET85 - 5G	Win 11
Zebra	ET65	Android 13, Build: 13-10-28.00-TG-U00-PRD-ATH-04

Zebra	TC78	Android 11 / 11-12-07.00-RG-U00-PRD-ATH-04
Zebra	TC27	Android 13, Build: 13-11-01.00-TG-U00-STD-ATH-04
Zebra	L10AX	Windows 11
Zebra TC56	TBD	Android 8.1.0
ZTE	ZTE MF971V 4G router	BD_MF97VV1.0B01
ZTE	MF833V, ZTE MF833V	BD_MF833V1.0.1B05
Zyxel	NR7101	FW: V1.00(ABUV.7)b3-dualsim-1221-4AP,Device OS/Kernel version: 3.10.14